

Areas with Asbestos Containing Materials (ACM) at Santa Ana College

Current as of 5/1/2012

A Building	
Building constructed in 1997, no ACM	
B Building	
Building constructed in 2001, no ACM	
C Building	
C102,104, 201, 204, 205, 206, 207, 208, 210,212, and 215.	Mastic associated with tan sheet flooring
Roof	Roof penetration mastic
C113	Mastic associated with 12"x12" gray vinyl floor tile
C106 vent hood	Transite panel assumed positive
D Building	
D435-3; D435-3A	Mastic associated with 12"x12"orange vinyl floor tile
E Building	
No ACM	
F Building	
No ACM	
G Building	
Exterior walls	Dash coat (ext. plaster)
G108-2; G108-4	9"x9" Tan vinyl floor tile and associated mastic
G105-6, ceiling space	TSI (thermal systems insulation) pipe wrap
G115 roof	Roof penetration mastic
G115, wall between M's and W's rm	TSI pipe wrap
H Building	
1 st fl corridor; H103; H106; 2 nd fl corridor; H202; H204; H205A	12"x12" gray vinyl floor tile and associated mastic
H110 basement stairway; H205; H210-2	9"x9" brown vinyl floor tile
Pipe access and wall cavities	TSI pipe insulation
I Building	
No ACM	
J Building	
J109-3	Tan floor sheeting
J101; J102; J109-1; J201; J201-1; J201-2; J203, J204	12"x12" tan floor tile and associated mastic
roof	Transite pipe presumed positive
K Building	
Classroom K201; K201-1 and K201-2	9"x9" green vinyl floor tiles
L Building	
Rooms L112-1 and L112-3	Chalkboard mastic
Above the ceiling on the original 1st floor portion of the library (east side). The asbestos containing material is above the drop ceiling in the old/original part of the library building. From the main reading room, it starts at the edge of the study rooms and includes everything east, including the Media Services area. The west side of the building, the 2 story structure that includes the math lab and study center, is asbestos free.	Fireproofing material
Throughout 2 nd floor	TSI elbows
Throughout 2 nd floor	Chalkboard mastic
L222-6	Vinyl sheet flooring
2 nd floor hallway	Blue Linoleum
Roof	Roofing material
Roof	Parapet wall material
Roof	Parapet cap sealant
Roof	Penetration mastic
M Building	
Throughout bldg, except Planetarium	9"x9" beige floor tile and associated mastic
M106 and Vestibule M100	
N Building	
Corridors; Choir rm; Theory Instruction Practice rms N107-N112; Tap Master; Computer rm; Music Lab ofc; N113; Band Room ofcs N114, N115,N116	9"x9" beige floor tile and associated mastic
Attic	TSI debris

Added 7/01/08

Areas with Asbestos Containing Materials (ACM) at Santa Ana College

Current as of 5/1/2012

Roof	Penetration mastic
Roof, parapet cap	Parapet cap mastic
P Building	
Costume rms P106-1; P106-3	9"x9' green floor tile and associated mastic
Theater lab/control booth east; P105-3; P202-1; P202-2; P202-3	Mastic associated with 12"x12" gray floor tile
P202-1; P202-2; P202-3	Mastic associated with 12"x12' green floor tile
R Building	
Rooms R-101, R101-1, R101-2, R103, R103-1, R105, R105-1, R105-2, R107, R107-1, R107-2, R109, R119-1, R119-2	Black tile mastic
Rooms R100, R109-1 and R111	9"x 9" dark green vinyl floor tile and associated mastic
Rooms R103-1, R109, R109-1, R111, R113, R114, R115, R117, R118, R118B, R120 R124, R126 and R128	9"x9" white vinyl floor tile and associated mastic
Throughout 1 st floor ceiling	Sprayed on fireproofing
Rooms R112, R112-1, R112-4	9"x 9" light green vinyl floor tile and associated mastic
Throughout 1 st floor	Approximately 17 asbestos wall panels
Throughout 2 nd floor ceiling	Sprayed on fireproofing
R207	12"x12" gray vinyl tile mastic, though tile tested negative
R207, R228-2	Lab Exhaust hood panels
R201, R202, R203-1, R204, R205, R206, R211, R215, R217, R218-5, R219, R224, R226, R228	9"x 9" white vinyl floor tile and associated mastic
R202-1, R218, R218-A, R218-1, R218-5, R220, R222 , R226-1, R226-2, R228-1W	9"x 9" light green vinyl floor tile and associated mastic
R200	9"x 9" dark green vinyl floor tile and associated mastic
Throughout 2 nd floor	Approximately 14 asbestos wall panels
Throughout 3 rd floor ceiling	Sprayed on fireproofing
R300, R301, R303, R303-4 , R304, R307, R307-2, R309, R318, R320-1, R322, R324, R328	9"x 9" white vinyl floor tile and associated mastic
R300	9"x 9" dark green vinyl floor tile and associated mastic
R302-1, R302-2, R302-3, R305, R314, R314-2, R328-2	9"x 9" light green vinyl floor tile and associated mastic
Throughout 3 rd floor	Approximately 10 asbestos wall panels
Penthouse/mechanical room	Vibration cloth and associated mastic
Penthouse/mechanical room	Elbows (approx 21)
Roof	AC penetration mastic
Roof	Elbows (approx 4)
S Building	
Structural steel member above the first and second floor ceiling running along the perimeter of the building.	There is some residual sprayed-on fireproofing on the steel member. The area has been fully encased.
Exterior and roof	Roof penetration sealant
T Building	
T203; T203-1 and T206	9"x 9" brown floor tile and associated mastic
T212 and T213	Green linoleum and associated mastic
T201	Tan linoleum and associated mastic
T103; T104; T105; T106	9"x 9" brown floor tile and associated mastic
T-107	Large asbestos-cement vent pipe from a former heat treat furnace
T201	Brown linoleum and associated mastic
Throughout Building	Thermal Insulated System (TSI) mudded elbows and T's located throughout the building, above the ceiling tile or at the ceiling.
U Building	
Throughout 1 st floor	12"x12" dark orange vinyl floor tile and mastic
Throughout 1 st floor	12"x12" white vinyl floor tile and mastic
Throughout 1 st floor	12"x12" blue vinyl floor tile and mastic
Throughout 1 st floor	12"x12" grey vinyl floor tile and mastic
Throughout 1 st floor	12"x12" red vinyl floor tile and mastic
U208-5, U208-6, U208-7A, U210, U211	12"x12" brown floor tile and mastic
Throughout 2 nd floor	12"x12" dark orange vinyl floor tile and mastic
Throughout 2 nd floor	12"x12" white vinyl floor tile and mastic
Throughout 2 nd floor	12"x12" blue vinyl floor tile and mastic
Throughout 2 nd floor	12"x12" grey vinyl floor tile and mastic
Throughout 2 nd floor	12"x12" red vinyl floor tile and mastic
roof	Penetration mastic presumed positive

Areas with Asbestos Containing Materials (ACM) at Santa Ana College

Current as of 5/1/2012

roof	Roofing material presumed positive
roof	AC mastic presumed positive
W Building	
W102-4 and n/s corridor near W102-6	12"x 12" beige floor tile and associated mastic
W102-7 and W102-8 M's room and shower; W102-6 and W102-1 W's room and shower; Gym and Custodial room	TSI mudded elbows and T's
Z Building	
Z102; Z104-1; Z104-2	9"x 9" green floor tile and associated mastic
Z106 and Z108	White linoleum flooring and associated mastic

The following locations have asbestos in an amount greater than 0.10% but less than 1% and are not considered asbestos containing material, according to Cal-OSHA. They may be regulated, however, if more than 100 square feet is disturbed at any given time

C Building	
C207, C208	Mastic associated with gray sheet flooring (<1% ACCM)
D Building	
1 st fl, except restrooms; rooms D201-214; D301-313; D315; D401-438	Drywall/drywall joint compound (<1% ACCM)
4 th fl M's and W's rooms	Interior plaster (<1% ACCM)
E Building	
None	

Areas with Asbestos Containing Materials (ACM) at Santa Ana College

Current as of 5/1/2012

H Building	
1 st and 2 nd fl plenums; H103-1; H107B	Drywall/drywall joint compound (<1%ACCM)
J Building	
J109-1; J201-204 and hallway	Drywall joint compound (<1%ACCM)
L Building	
Throughout 1 st floor	Smooth plaster (<1%ACCM)
Throughout 1 st floor	Drywall (<1%ACCM)
C Building	
Interior walls and ceiling throughout building: Attic	Drywall/drywall joint compound (<1%ACCM)
P Building	
Throughout building	Drywall/drywall joint compound (<1%ACCM)
P106	Mastic associated w/ brown baseboard (<1%ACCM)
P202-1	Mastic associated w/ 1'x1' black ceiling tile (<1%ACCM)
R Building	
Throughout 2 nd floor ceiling	Pipe insulation fittings (<1%ACCM)
R218, R226	12"x 12" brown floor tile (<1%ACCM)
R200, R209, R211, R218, R218-1, R218-2, R218-3, R218-A, R222	Brown baseboard mastic (<1%ACCM)
Throughout 3 rd floor ceiling	Pipe insulation fittings (<1%ACCM)
R301-1A, R303, R303-1, R303-1S	Drywall and joint compound (<1%ACCM)
S Building	
Throughout 1 st floor	Drywall with taping mud (<1%ACCM)
Throughout 2 nd floor	Drywall with taping mud (<1%ACCM)
T Building	
Second floor	Brown baseboard throughout 2 nd floor (<1%ACCM)
Second floor	Drywall and drywall joint compound throughout 2 nd fl (<1%ACCM)
Firewall	n/s center wall (<1%ACCM)
1 st floor	Drywall and drywall joint compound throughout 1 st fl (<1%ACCM)