

2323 North Broadway • Santa Ana, CA 92706 -1640 • (714) 480-7300 • www.rsccd.edu

Santa Ana College • Santiago Canyon College

#### REQUEST FOR QUALIFICATIONS/REQUEST FOR PROPOSAL (RFQ/RFP) #1920-271

#### ARCHITECTURAL AND ENGINEERING SERVICES – BARRIER REMOVAL PROJECTS AT SANTIAGO CANYON COLLEGE

#### Addendum No. 02

#### Issued: July 10, 2020

The following changes, additions, deletions, or corrections shall become part of the above-mentioned RFQ/RFP:

A. The RFQ/RFP Schedule has been revised as follows:

Event / Occurrence	Deadline
Deadline for Consultants to submit	July 21, 2020 by 4:00pm
questions regarding this RFQ/RFP	
Deadline for Consultants to submit	August 20, 2020 by 4:00pm
Responses	
District to interview Consultant(s)	August/September 2020
(Estimated)	
District to finalize recommendation for	September/October 2020
District Board of Trustees	
District Board of Trustees approves	TBD
successful Consultant	


- B. The following are responses to questions received from various firms:
  - 1. I'm reaching out to see if there's a day and time we can schedule a site walk at Santiago Canyon College for the Barrier Removal Projects for RFP #1920-271.?

Answer: Job walks will not be scheduled for the Barrier Removal Projects listed in RFP #1920-271. Photographs and keyed plans are provided in Exhibits A, B, and C in lieu of inperson observation.

#### Enc.

Exhibit A - Existing Project Photos - Barrier Removal Lots 2 and 7 Crosswalk Repairs at Santiago Canyon College Exhibit B - Existing Project Photos - Building D Restrooms (Multi-User) Exhibit C - Existing Project Photos - Building D Restroom (Single-User)

# **EXHIBIT A**





#### Photograph #1

Blended transition and crosswalk on the south side of Parking Lot 2.



#### Photograph #2

Curb ramp, street markings, and crosswalk on the south side of Parking Lot 2.



## Photograph #3

Curb ramp with detectable warning tiles on the east side of the Parking Lot 2 crosswalk.



#### Photograph #4

Curbed planter south of the Parking Lot 2 crosswalk blended transition.



## Photograph #5

Curbed planter irrigation boxes, heads, and vents.



#### Photograph #6

The south side of the curbed planter running north-south from Parking Lot 2 to the accessible parking on Loop Road.



## Photograph #7

Concrete sidewalk north of the accessible parking on Loop Road.




#### Photograph #8

Parallel curb ramp and crosswalk at the Parking Lot 4 entrance.



## Photograph #9

Concrete sidewalk on the south side of Parking Lot 4.




## Photograph #10

Concrete sidewalk on the south side of Parking Lot 4.



## Photograph #11

Concrete sidewalk on the south side of Parking Lot 4.





## Photograph #1

Curb ramp and crosswalk at Parking Lot 7.



#### Photograph #2


Blended transition on the north side of the Parking Lot 7 crosswalk.





# Photograph #3


Crosswalk and street markings at Parking Lot 7.

## **EXHIBIT B**










## Photograph #1

First floor multi-user restroom entry alcove and drinking fountain.



## Photograph #2

The women's first floor multi-user restroom entrance.



## Photograph #3

The women's first floor multi-user restroom.



## Photograph #4

The women's first floor multi-user restroom lavatory and mirror bank.



#### Photograph #5

The women's first floor multi-user restroom partitions.




#### Photograph #6

The women's first floor multi-user restroom structural steel headrail partition support and suspended ceiling.



## Photograph #7

The women's first floor multi-user restroom accessible stall.



## Photograph #8

The men's first floor multi-user restroom entrance.



## Photograph #9

The men's first floor multi-user restroom.



## Photograph #10

The men's first floor multi-user urinal bank.



## Photograph #11

The men's first floor multi-user lavatory and mirror bank.




#### Photograph #12

The men's first floor restroom structural steel headrail partition support and suspended ceiling.



## Photograph #13

The men's first floor restroom accessible stall.



## Photograph #14

The chamfered corner on the exterior of the second-floor women's multi-user restroom.



## Photograph #15

The women's second floor multi-user restroom entrance.



## Photograph #16

The women's second floor multi-user restroom.




## Photograph #17

The women's second floor multi-user restroom lavatory bank.




## Photograph #18

The women's second floor multi-user restroom stall.




## Photograph #19

The men's second floor multi-user restroom entrance.



## Photograph #20

The men's second floor multi-user restroom.



## Photograph #21

The men's second floor multi-user restroom partitions and structural steel headrail support.



# Photograph #22

The men's second floor multi-user restroom urinal bank.



## Photograph #23

The men's second floor restroom lavatory bank.



## Photograph #24


The men's second floor multi-user restroom accessible stall.





# Photograph #25

The men's second floor restroom suspended ceiling grid and drop in tiles, similar to all multiuser restrooms on the first and second floor.

# **EXHIBIT C**








## Photograph #1

The women's changing room/ restroom door.



## Photograph #2

The women's changing room entrance.



## Photograph #3

The women's changing room east wall.




## Photograph #4

The women's changing room at the north wall and vanity counter.



## Photograph #5

The women's changing room west wall.




## Photograph #6

The women's changing room single user restroom stall door.




## Photograph #7

The women's changing room single user stall south and west wall.




## Photograph #8

The women's changing room single user stall restroom accessories.



## Photograph #9

Alcove between the men's and women's changing room with the drinking fountain removed.



## Photograph #10

The men's changing room/restroom entrance.



## Photograph #11

The men's changing room east wall.



## Photograph #12

The men's changing room south wall.



## Photograph #13

The men's changing room west wall.



#### Photograph #14

The men's changing room single user restroom stall at the north and west walls.

End of Addendum No. 02